

## Retrofitting Existing Challenger Model CL10 or 39000 Two-Post Lifts with XP9 Drive-Over Style Pads for Honda Express Service Lifts

The Challenger XP9 drive-over style pad can be retrofitted to any existing Challenger model CL10 or 39000 two-post lift.

This is done by identifying the model number and serial number of your lift. Locate the model number and serial number on the top cover plate of the lift (location is indicated in the graphic below).

Once you have obtained the model and serial numbers and recorded them, contact the Honda Tool and Equipment Program at 888-424-6857 and we will verify the appropriate components needed to retrofit your lift.

